

P5000i Extension Installation

Figure 1-1: P5000i Extension Parts



Installation

- Step 1** The back end of the P5000i probe features two screw depressions on each side of the probe. Mount an extension part onto the probe by orienting it so that its posts are aligned with the screw depressions on one side, fit the posts into the screw depressions, and then press the USB cable into the track on the mounted extension part.



- Step 2** Align the second extension part with the two screw depressions on the opposite side of the probe, and then starting from the back, press the extension parts together until the posts of second part are fitted into the screw depressions.

